

Version 2.2.1b

Release date: May 12, 2008

New in this version:

This is a maintenance version and does not contain any new feature over v2.2.0.

Bug Fixes:

This version contains a number of bug fixes over version 2.2.0. These bug fixes are detailed below.

Bug #	Subject
622	Wrong completion code returned by Get LED Color Capabilities for an inexistent LED in test #115
621	Test #3 fails when it sees a Telco Alarm Input sensor
620	Test #113 fails in lamp test mode only for AMC
619	Led 3 does not return to its previous state during testing on AMC in test #108
618	Test #14 fails for any managed FRU except FRU 0

Known Issues in this version:

This version contains the following known bugs.

Bug #	Subject
422	Test #600 intermittent internal error
423	Tester does not restore the custom fields of Chassis Info during Write FRU Data.
130	Test #13: Shelf Manager filters some event – quick changing values for sensors makes the test fail.
131	Test #201: should not require a blade address, since it is applicable for ShMC only.