

Version 2.2.1

Release date: September 23, 2008

New in this version:

This is a maintenance version and does not contain any new feature over v2.2.1b. This release contains HPM beta test cases.

Bug Fixes:

This version contains a number of bug fixes over version 2.2.1b. These bug fixes are detailed below.

Bug #	Subject
1379	Test #613 and test #612 fail as Get AMC Port State command is unable to return more than 3 link information in a single response
1378	Test # 201 skips if the Init Scanning bit is equal to 0b
830	Test #101 displays wrong information for a non zero managed FRU

Known Issues in this version:

This version contains the following known bugs.

Bug #	Subject
422	Test #600 intermittent internal error
423	Tester does not restore the custom fields of Chassis Info during Write FRU Data.
130	Test #13: Shelf Manager filters some event – quick changing values for sensors makes the test fail.
131	Test #201: should not require a blade address, since it is applicable for ShMC only.