

Version 2.2.0

Release date: February 12, 2008

New in this version:

This version adds a new test category for **HPM.1** testing. This test category contains 5 IPMC test cases and 5 MMC Test cases. The HPM.1 MMC test cases are still experimental. Also this version implements some of the critical differences in **PICMG3.0 R3.0** manageability section.

Bug Fixes:

This version contains a number of bug fixes over version 2.1.1b. These bug fixes are detailed below.

Bug #	Subject
237	Test #315 always uses 0x00 as the IPMB address of the backup Shelf Manager
424	Test #315 aborts test due to spurious logs.
201	Issues in retransmitted messages

Known Issues in this version:

This version contains the following known bugs.

Bug #	Subject
422	Test #600 intermittent internal error
423	Tester does not restore the custom fields of Chassis Info during Write FRU Data.
130	Test #13: Shelf Manager filters some event – quick changing values for sensors makes the test fail.
131	Test #201: should not require a blade address, since it is applicable for ShMC only.